

To: McKean, Deborah[mckean.deborah@epa.gov]
From: Wall, Dan
Sent: Sat 8/8/2015 3:05:50 PM
Subject: FW: Gold King Mine Methods

From: Jacob Miller [mailto:jacob.miller@greenanalytical.com]
Sent: Friday, August 07, 2015 9:17 AM
To: Wall, Dan
Subject: FW: Gold King Mine Methods

From: Pryhoda, Moira [mailto:Moira.Pryhoda@WestonSolutions.com]
Sent: Friday, August 07, 2015 8:29 AM
To: Jacob Miller
Cc: Butterfield, W. Scott
Subject: Gold King Mine Methods

Hi Jacob,

Here is an updated list of methods and which metals we need by each method:

200.7

Al

Ca

Fe

K

Mg

Na

-

200.8

Ag

As

Ba

Be

Cd

Co

Cr

Cu

Mn

Mo

Ni

Pb

Sb

Se

Tl

V

Zn

7470/7471/747 (I think this should be 245.1 not 7471 but it's the same technique either way
"CVAA."

Hg

As Craig and Dan told you, we won't be needing TDS and TSS right now, although it might be needed in the future.

Thanks!

Moira Pryhoda

Weston Solutions, Inc.

1435 Garrison St, Ste 100

Lakewood, CO 80215

Ph: 303-729-6112

Cell: 508-904-7579

CONFIDENTIALITY: This email and attachments may contain information which is confidential and proprietary. Disclosure or use of any such confidential or proprietary information without the written permission of Weston Solutions, Inc. is strictly prohibited. If you received this email in error, please notify the sender by return e-mail and delete this email from your system. Thank you.